

Phone: (07) 4955 9100

Email: admin@qldccs.com.au

www.qldccs.com.au

New and modified structures were required at DRCT to improve Sediments collection and retention, maintenance access, water recovery and serviceability within the Industrial Dam, 553B The various construction and modification tasks undertaken over the four month project included 10 Pit- Inlet Gates Installation, Sill une roun invituitiones Stabs, Dewatering System 10-Channel, Causeway, Raising, Drying Stabs, Dewatering System 10-Channel, Causeway, Raising, Drying Stabs, Dewatering System, 10-Channel, Causeway, Raising, Drying Stabs, Dewatering System, 10-Channel, Causeway, Cause Traisment Cells, Sump Filter Wall, Spill Way V-notch Infill, Pittl A Substation and Coal Collection Pit. Modifications and Substation SS3B Transformer Vard Uperade.

casestudy LOCATION OF JOB: Dairymple Bay Coal CLIENT: Vassallo Constructions

Terminal, QLD CONTRACT VALUE: \$1.06M

DBCT Management





